


# INSPECTION REPORT



For the Property at:  
**321 TYPICAL STREET**  
TORONTO, ON

---

Prepared for: VALUED CLIENT  
Inspection Date: Tuesday, October 2, 2012  
Prepared by: Lisa Simkins



Meticulous Inspections Inc.  
11 Wilkins Ave  
Toronto, ON M5A 3C2  
647-287-1962  
[www.meticulousinspections.ca](http://www.meticulousinspections.ca)  
[info@meticulousinspections.ca](mailto:info@meticulousinspections.ca)

# INTRODUCTION

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

**Note:** For the purpose of this report the building is considered to be facing **North**.

## OUR PHILOSOPHY

The inspection is aimed at finding functional items that could be improved to increase the safety, comfort and value of your home.

## SCOPE

A home inspection is a survey of the major systems of the house including roofing, exterior, structural, interior, structure, electrical, plumbing, heating, cooling, insulation and ventilation. In the short period of inspection time, as much information is gathered as practical to report on conditions. The findings are a snapshot of the visible conditions of the installed systems at the time of inspection.

## EXPERT ADVICE

Generally, I also encourage home owners to have specialists and qualified contractors inspect various systems of the house, for an expert opinion, especially on older or dysfunctional systems. Several Ontario regulatory safety associations will provide inspection services and lists of licensed/certified contractors. These include:

- Technical Standards and Safety Authority (TSSA), will inspect gas and oil burning supply systems, such as those that service furnaces, hot water heaters and fireplaces. [www.tssa.org](http://www.tssa.org) 1-877-682-8772
- Electrical Safety Authority (ESA), will inspect electrical systems. [www.esasafe.com](http://www.esasafe.com) 1-877-372-7233

There are some important things you should do when taking possession of a home. These are detailed in the Priority Maintenance document, which you can access by clicking on the link below.

[Maintenance schedule for your home](#)

## DESCRIPTION OF REPORT

The report that follows includes a description of the systems and components in the house as well as any Limitations that may have restricted the inspection. General limitations are spelled out in the Home Inspection Contract.

The most important part of the report are the Recommendations in each section. It is here that defects are identified and improvements may be suggested. NOTE: there are many clickable links throughout the report where you can access more information about house systems or deficiencies. You can also move quickly between the various house systems in the report by clicking on the coloured tabs at the top of each page.

As you read the report, we encourage you to contact me with any questions about the report or the home.

# INTRODUCTION

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## HIGHLIGHTS

This section provides a snapshot of potentially significant issues from a cost or safety standpoint. More detailed findings are listed in the body of the report. Please read the entire report; it will assist you to plan and budget for repairs. For instance, if a major and minor item are listed in a section, it will likely be cost effective for you to have a contractor visit to address both at the same time, to reduce service calls.

## SITE

We were advised that the semi-detached house is approximately 90 years old.

## ROOF

The front north facing roofing is old and at the end of it's lifespan. The main front north facing peaked portion, front porch and bay window roofing should be stripped and replaced. Flashing should be replaced or repaired at that time. The rear flat roof needs some sealing at the edges. The rear facing shingles appear to be intact. Note that severe weather events or damage can cause roof leaks at any time.

## EXTERIOR

The house should have improved sealing in siding and walls around windows, doors and joints to reduce chances of water infiltration as described in the report. Tuckpointing repairs and gutter cleaning are also recommended to help protect against water. Some windows and doors need fixing of screens and operation. The basement stairwell needs a handrail, and porch rail requires fixing. The deck support appears insufficient and should be improved, as well the deck floor boards are old and showing signs of rot. The downspout and basement stairwell drainage system should be evaluated for improvement for protecting the basement from water infiltration.

## STRUCTURE

The house has a brick foundation with timber frame, aluminum cladding and brick veneer front. Improvement of the firewall in the attic is recommended. Other minor repairs and monitoring are suggested to help protect the structure.

## ELECTRICAL

Due to the age of the house and modifications done over time, the electrical panel and distribution system should be thoroughly inspected by a licensed electrician. For example, there is some questionable wiring within the distribution panel, and a burned electrical receptacle. Cover plates should be installed on any open receptacles or boxes. The number of receptacles is typical for the age of the house, however modern practices require more circuits for receptacles and lights. Some issues found are detailed within the body of this report.

## HEATING

The gas fired boiler is 10 years old with a typical life expectancy of 25-50 years. There is some rust at the burners and pipes, and the boiler, pipes and radiators should be checked at the start of each heating season by a qualified plumbing and heating technician. The water distribution pipes are wrapped in material which is ripped and possibly contains asbestos. This damaged material may have released asbestos and should either be encapsulated or removed. Consult an asbestos removal specialist for advice and estimates. Note if the asbestos material is left in place, it may affect the resale value of the house, although encapsulation will provide protection from exposure. Removal is more economical if renovations are to be done as well. See the information brochure in the appendix of the report.

# INTRODUCTION

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## COOLING

The ductless air conditioning system is about 7 years old. Annual inspection and servicing by an HVAC technician at the start of the cooling season is recommended. Product information and manuals are included in the appendix.

## INSULATION

The attic is insulated with blown cellulose, to approximately R-28. Wall insulation could not be determined, but based on the known history of the house and visual clues, may be missing. Blown cellulose could be added into the walls if desired.

## PLUMBING

The main supply pipe appears to be galvanized, and may be causing low flow in the house. Recommend replacement with copper supply pipe from the city piping to the meter. Several minor repairs of piping and fixtures are recommended.

## INTERIOR

The 24 year old windows are functional but need some repairs. The rear doors of the house are in poor condition and the main floor kitchen counter is water damaged around the sink. The basement bathroom fan requires an exterior vent termination. Other items are noted in the report.

## REPAIRS

There are published sources for repair and renovation estimates. One of these is [www.Ontariocontractors.com](http://www.Ontariocontractors.com).

See also:

[Home Improvement - ballpark costs](#)

# ROOFING

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE


## Description

### Sloped roofing material:

- [Asphalt shingles](#)

Shingles on peaked roof, over porch and bay window.

According to current owner, the rear shingles were replaced in 2002.



*Rear of peaked roof*



*Roof peak*



*Front of peaked roof*

- [Wood shingles/shakes](#)

visible under front asphalt shingles

# ROOFING

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*Layers of roofing over front porch*

- [Strip when reroofing](#)

## Flat roofing material:

- [Roll roofing](#)  
on rear flat roof.



*Roll roofing*



## Limitations

### Roof inspection limited/prevented by:

- Lack of access (too high/steep)
- Front portion of main peaked roof could not be safely walked on.

### Inspection performed:

- By walking on roof
- on the flat roof and rear portion of peaked roof accessible from flat roof.
  - With binoculars from the ground

of the front portion of peaked roof.
  - From roof edge

of the front porch and bay window.

## Recommendations

### SLOPED ROOFING \ Asphalt shingles


#### 1. Condition: • [Old, worn out](#)

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Front Porch

**Task:** Replace

**Time:** Immediate



[Click on image to enlarge.](#)

# ROOFING

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*Old, worn out at front*

**2. Condition:** • [Cupping, curling, clawing](#)

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Front

**Task:** Replace

**Time:** Immediate



*Curling shingles on front of peak*

## **SLOPED ROOF FLASHINGS \ Valley flashings**

**3. Condition:** • [Rust](#)

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Transition of front porch to bay window

**Task:** Replace



# ROOFING

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*Rust*

## **SLOPED ROOF FLASHINGS \ Roof/wall flashings**

### **4. Condition:** • [Damage, loose, open seams, patched](#)

Rainwater running down wall may seep behind flashing and into porch roof structure.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Front

**Task:** Repair



*opened seam of flashing*

# ROOFING

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## **FLAT ROOFING \ Roll roofing**

**5. Condition:** • Tree overhang - trim back

**Implication(s):** Trees drop debris which can promote moisture retention, and overhanging tree branches can rub on roofing in the wind, causing wear and tear.

**Location:** Rear

**Task:** Correct

**Time:** Immediate



*Roll roofing*

**6. Condition:** • [Openings at seams or flashings](#)

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** West

**Task:** Repair



*Openings at flashing of flat roof*

# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description

Gutter & downspout material: • [Aluminum](#)

Gutter & downspout discharge: • [Below grade](#)

Wall surfaces - masonry: • [Brick](#)

Wall surfaces : • [Metal siding](#)

Soffit and fascia: • [Metal](#)

Walkway: • Concrete

Deck: • Raised • Wood • Railings


## Recommendations

### ROOF DRAINAGE \ Gutters

7. Condition: • [Clogged](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Rear Exterior



[Click on image to enlarge.](#)



*Clogged rear eavestrough*


## ROOF DRAINAGE \ Downspouts

### 8. Condition: • [Downspouts discharging below grade](#)

Potential source of basement leakage if underground drains back up.

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Throughout



[Click on image to enlarge.](#)

# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## WALLS \ Metal siding

**9. Condition:** • Gap

**Implication(s):** Increased chance of water penetrating wall.

**Location:** West

**Task:** Improve

**Time:** Immediate



*Gap in siding*

**10. Condition:** • [Flashing and caulking defects](#)

**Location:** Throughout around doors and windows and on sides of chimney

**Task:** Improve



# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



[Click on image to enlarge.](#)



*open joints around frames*



*unsealed areas*

## WALLS \ Brick, stone and concrete

### **11. Condition:** • [Mortar deterioration](#)

Small areas of mortar deterioration.


**Location:** Various

**Task:** Repair (tuck pointing)

**Time:** Yearly inspection by owner and tuck pointing by qualified mason



## Repointing



[Click on image to enlarge.](#)



*Typical mortar deterioration*

### EXTERIOR GLASS \ Exterior trim

**12. Condition:** • [Caulking loose, missing or deteriorated](#)

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Increased heating and cooling costs

**Location:** Basement windows

**Task:** Seal joints

**Time:** Immediate

# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*Caulking loose, missing or deteriorated*


## EXTERIOR GLASS \ Exterior drip caps

13. Condition: • [Missing](#)

Implication(s): Chance of water damage to contents, finishes and/or structure

Location: Throughout

Task: Provide



[Click on image to enlarge.](#)

# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*typical trim over opening with no drip edge*

## EXTERIOR GLASS \ Storms and screens

**14. Condition:** • screen out of place

**Implication(s):** pests

**Location:** West Basement

**Task:** Repair

**Time:** Regular maintenance



*basement window*

## DOORS \ Doors and frames

**15. Condition:** • [Loose or poor fit](#)

**Implication(s):** Chance of damage to finishes and structure

**Location:** Basement

**Task:** Repair

## DOORS \ Exterior trim

**16. Condition:** • [Caulking missing, deteriorated or loose](#)

**Implication(s):** Chance of damage to finishes and structure

**Location:** Kitchen

**Task:** Repair/seal

**Time:** immediate



*sliding door trim in poor condition*

**17. Condition:** • [No drip edge](#)

**Implication(s):** Chance of damage to finishes and structure

**Location:** Throughout

**Task:** Improve

## DOORS \ Exterior drip caps

**18. Condition:** • [Missing](#)

**Implication(s):** Chance of damage to finishes and structure

**Location:** Throughout

**Task:** Improve

**Time:** Less than 1 year

## 19. Condition: • [Ineffective](#)

**Implication(s):** Chance of damage to finishes and structure

**Location:** Throughout

### **BASEMENT ENTRANCES \ Basement stairwells**


## 20. Condition: • [Drains missing, clogged or undersized](#)

Owner reports inadequate drainage.


**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** Basement

**Task:** Further evaluation by drain specialist.



[Click on image to enlarge.](#)



[Click on image to enlarge.](#)



# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



## 21. Condition: • [Guard and handrail problems](#)

missing

**Implication(s):** Fall hazard

**Location:** South Basement

**Task:** Provide

**Time:** Immediate



# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*No handrail in basement stairwell*

## **PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Beams**

**22. Condition:** • Beam not secured to bracket

**Implication(s):** Structure may move

**Location:** Throughout Exterior

**Task:** Improve



*Fastening missing*


## PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Joists

### 23. Condition: • [Ledgerboard problems](#)


Attachment points of deck appears insufficient for proper support.

**Implication(s):** Weakened structure | Chance of movement

**Task:** Further evaluation



[Click on image to enlarge.](#)



West side of deck



East side of deck

# EXTERIOR

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Floors

**24. Condition:** • [Rot or insect damage](#)

**Location:** Throughout

**Task:** Replace deck floor boards



*Rot damage in deck*

## PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Steps and landings

**25. Condition:** • [Rot or insect damage](#)

**Implication(s):** Weakened structure | Material deterioration

**Location:** Yard

**Task:** Replace deteriorated boards on steps

## PORCHES, DECKS, STEPS, PATIOS AND BALCONIES \ Handrails and guards

**26. Condition:** • [Loose](#)

Railing supports are deteriorating. There should be no wiggle in deck railings.

**Implication(s):** Fall hazard

**Location:** Rear Deck

**Task:** Repair and monitor

**Time:** Immediate

# EXTERIOR

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*rear porch nails coming out of support*

## LANDSCAPING \ Driveway

**27. Condition:** • [Unsealed gap at house](#)

**Implication(s):** Chance of water damage to contents, finishes and/or structure

**Location:** West First Floor

**Task:** Seal with appropriate caulk or concrete patch

**Time:** Immediate





## Description

**Configuration:** • [Basement](#)

**Foundation material:** • [Brick](#)

**Floor construction:** • [Joists](#) • [Concrete](#)

**Exterior wall construction:** • [Wood frame, brick veneer](#)

**Roof and ceiling framing:** • [Rafters/roof joists](#)

## Limitations

**Attic/roof space:** • Inspected from access hatch

## Recommendations

### FOUNDATIONS \ Foundation

**28. Condition:** • [Wood/soil contact](#)

Remains of wood post in foundation at fence line. This makes structure more vulnerable to water and pests.

**Location:** West Exterior

**Task:** Repair. ie. remove external portion of wood and reseal wall



*Wood/soil contact*

### WALLS \ Party walls

**29. Condition:** • [Incomplete in attic](#)

Improve seal around edges

**Implication(s):** Increased fire hazard

**Location:** East Attic

**Task:** Improvement recommended

**Time:** Immediate



*example of gaps in firewall of attic*

## ROOF FRAMING \ Sheathing

### **30. Condition:** • [Water stains](#)

This may have occurred before rear roof was redone, however it is good practice to inspect yearly and during heavy rainfalls to determine if staining is increasing or wood is wet

**Implication(s):** Material deterioration

**Location:** Attic

**Task:** Monitor



*Water stains*



## Description

**Service entrance cable and location:** • [Overhead](#)

**Main disconnect/service box rating:** • [100 Amps](#)


**System grounding material and type:** • [Copper - water pipe](#)

**Distribution panel type and location:**

• [Breakers - basement](#)



*Breakers - basement*




*Inside panel cover - basement*

**Distribution wire material and type:**

• [Copper - non-metallic sheathed](#)

• [Aluminum - non-metallic sheathed](#)

Visible in electrical panel - 30 Amp labelled "Dryer"



*Aluminum - non-metallic sheathed*

## Type and number of outlets (receptacles):

- [Grounded and ungrounded - minimal](#)

Typically one or two receptacles per room.

**Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI):** • No GFCI • No AFCI

**Smoke detectors:** • [Present](#)

## Recommendations

### SERVICE BOX, GROUNDING AND PANEL \ System grounding


**31. Condition:** • [No jumper for meters and valves](#)

Water meter

**Implication(s):** Electric shock

**Location:** Front Basement

**Task:** Provide



[Click on image to enlarge.](#)

### SERVICE BOX, GROUNDING AND PANEL \ Distribution panel


**32. Condition:** • [Rust or water in panel](#)

Slight rust staining in bottom right corner of panel.

**Implication(s):** Electric shock | Fire hazard

**Location:** Basement

**Task:** Ask electrician to check inside main breaker section



[Click on image to enlarge.](#)

## SERVICE BOX, GROUNDING AND PANEL \ Panel wires


**33. Condition:** • Suspect

**Implication(s):** Safety - wiring appears unusual and possibly discoloured from heat damage.

**Location:** Basement

**Task:** Have panel inspected by licensed electrician

**Time:** Immediate



*only one wire on double pole breaker*



*Discoloured wires*



## **DISTRIBUTION SYSTEM \ Wiring - installation**

### **34. Condition:** • [Open splices](#)

**Implication(s):** Electric shock | Fire hazard

**Location:** Basement Utility Room



*Unprotected splice*

### **35. Condition:** • [Not well secured](#)

Electrical cable tied to water line with electrical tape

**Implication(s):** Electric shock | Fire hazard

**Location:** Utility Room

**Task:** Remove electrical tape. Support cable appropriately

**Time:** Immediate



*Not well secured*

**36. Condition:** • [Extension cord used as permanent wiring](#)

**Implication(s):** Electric shock | Fire hazard

**Location:** West Living Room and various other locations

**Task:** Improve; reduce number of extension cords used, ensure any extension cords are newer and CSA labelled. Ideally, install more electrical outlets so that extension cords are not required.

**DISTRIBUTION SYSTEM \ Lights**

**37. Condition:** • [Inoperative](#)

A live light fixture with empty sockets is a shock hazard. Install light bulbs in all sockets. If fixture is too bright, use lower amperage bulbs.

**Implication(s):** Inadequate lighting

**Location:** Basement Bathroom

**Task:** Ensure all sockets are working. If they are not working there may be a wiring problem which could be a fire hazard. Repair by electrician. Fixture may need to be replaced.

**Time:** Immediate



*Inoperative and missing bulbs*

**DISTRIBUTION SYSTEM \ Outlets (receptacles)**

**38. Condition:** • [Reversed polarity](#)


Receptacle tester indicates wiring is incorrect.

**Implication(s):** Electric shock

**Location:** Basement Bathroom

**Task:** Repair by electrician.

**Time:** Immediate

**Reversed polarity**

when the polarity is reversed, the wide receptacle slot is (incorrectly) hot and the narrow slot is neutral - this is not uncommon when people forget that the black wire should be attached to the receptacle's brass screws

[Click on image to enlarge.](#)

**39. Condition:** • [Ungrounded](#)**Location:** Various**Task:** Upgrade**Time:** Immediate

*Ungrounded 2 prong type*



**40. Condition:** • [Ground needed for 3-slot outlet](#)

**Implication(s):** Electric shock

**Location:** Northwest Living Room and upstairs bathroom

**Task:** Repair

**Time:** Immediate

**41. Condition:** • [Loose](#)

**Location:** Basement Laundry Area

**Task:** Mount securely

**Time:** Immediate



*Loose receptacle*

**42. Condition:** • [Overheating](#)

**Implication(s):** Fire hazard

**Location:** Basement

**Task:** Further evaluation

**Time:** Immediate




*Evidence of electrical overheating*

**43. Condition:** • [No GFI \(Ground Fault Interrupter\)](#)

**Implication(s):** Electric shock

**Location:** Kitchen, bathrooms, exterior

**Task:** Upgrade



[Click on image to enlarge.](#)

## DISTRIBUTION SYSTEM \ Outlets (receptacles) - number or location

### 44. Condition: • [Too few outlets](#)

No receptacles over countertops

**Implication(s):** Nuisance

**Location:** Kitchens and most rooms

**Task:** Improve

## DISTRIBUTION SYSTEM \ Cover plates

### 45. Condition: • [Missing](#)

Cover plates prevent accidental contact with wiring. Photos illustrate several locations.

**Location:** Various

**Task:** Install plates

**Time:** Immediate



Basement ceiling switch



Upstairs Bedroom receptacle



Boiler electrical box

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## **DISTRIBUTION SYSTEM \ Smoke detectors**

**46. Condition:** • Test operation monthly

**Implication(s):** Fire safety

**Location:** All floors

**Task:** Service annually

# HEATING

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description

**Fuel/energy source:** • [Gas](#)

**System type:** • [Boiler](#)

**Boiler manufacturer:**

• Weil McLain

*Model number:* CGI4PIN52 *Serial number:* CP4262572

**Heat distribution:** • [Radiators](#)

**Approximate capacity:** • [85,000 BTU/hr](#)

**Efficiency:** • [Mid-efficiency](#)

**Approximate age:** • [10 years](#)

**Typical life expectancy:** • Boiler (cast iron) 25 to 50 years

**Main fuel shut off at:** • Meter • Basement

**Fireplace:**

• Wood-burning fireplace - not in service

blocked with Styrofoam

• Non-functional

**Chimney/vent:** • [Metal](#) • Sidewall venting

**Combustion air source:** • Interior of home

## Recommendations

### GAS HOT WATER BOILER \ Gas burners

**47. Condition:** • [Rust](#)

Rust flakes indicate corrosion is occurring. Have boiler system evaluated by a qualified gas boiler technician

**Implication(s):** Shortened life expectancy of material | Material deterioration

**Location:** Furnace Room

**Task:** Further evaluation

**Time:** Immediate



# HEATING

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*Rust below burners*

## GAS HOT WATER BOILER \ Pressure relief valve

**48. Condition:** • [No pipe extension](#)


There should be a pipe attached to this valve to direct water down close to the floor in case of overheating

**Implication(s):** Steam explosion

**Location:** Basement

**Task:** Provide

**Time:** Immediate



[Click on image to enlarge.](#)

# HEATING

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*No pipe extension*

## GAS HOT WATER BOILER \ Pipes

**49. Condition:** • [Pipe wrap damaged - possibly contains asbestos](#)

**Implication(s):** Asbestos in material is a health hazard if particles from wrapping become airborne.

**Location:** Basement

**Task:** Encapsulate or remove wrapping by asbestos removal experts

**Time:** Immediate



*Boiler water pipe wrap partially removed*



*Boiler pipe wrap*



*Boiler pipe wrap torn above cabinet*

**50. Condition:** • [Rust](#)

Monitor piping for leaks.


Connections between cast iron piping and copper should have dielectric fittings to prevent corrosion by contact between dissimilar metals. Consult with plumbing and heating gas boiler specialist.

**Implication(s):** Chance of water damage to contents, finishes and/or structure | Increased heating costs | Reduced comfort

**Location:** Various Basement Laundry Area

**Task:** Further evaluation Monitor

**Time:** Less than 1 year



[Click on image to enlarge.](#)

# HEATING

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



*Rust at boiler pipe connection*

## GAS HOT WATER BOILER \ Radiators, convectors and baseboards


**51. Condition:** • Poor Support

**Implication(s):** Inadequate supports may cause strain on piping and potential damage or injury if support fails.

**Location:** Second Floor Bathroom

**Task:** Improve

**Time:** Immediate



*Rad legs poorly supported*



*Tied to wall with wire*

# HEATING

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## 52. Condition: • [Cold](#)

Radiator does not heat up evenly, may need to be bled to remove trapped air.

**Implication(s):** Increased heating costs | Reduced comfort

**Location:** Front Second Floor Bedroom

**Task:** Further evaluation, service by qualified plumbing and heating technician.

**Time:** Immediate



# COOLING & HEAT PUMP

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description


**Air conditioning type:** • [Ductless system](#)

**Manufacturer:** • Mitsubishi

**Model number:** MUM 18NW **Serial number:** 46903093



Indoor unit



A/C exterior data plate



Outdoor unit - Compressor and fan

**Cooling capacity:** • [18,000 BTU/hr](#)

# COOLING & HEAT PUMP

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

**Compressor approximate age:** • 7 years

## Limitations

**Inspection limited/prevented by:** • Low outdoor temperature

# INSULATION AND VENTILATION

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

## Description

### Attic/roof insulation material:

- [Cellulose](#)

Approximately 8" depth insulation in attic



*Attic insulation*



*Cellulose insulation*

Attic/roof insulation amount/value: • [R-28](#)

Attic/roof ventilation: • [Roof vent](#)

Wall insulation material: • Not determined

## Limitations

Attic inspection performed: • From access hatch

## Recommendations


### ATTIC/ROOF \ Hatch

53. Condition: • [Not insulated and not weatherstripped](#)


Location: Second Floor Hallway Closet

Task: Improve

Time: Less than 1 year



[Click on image to enlarge.](#)



*Attic hatch from above*

## WALLS \ Insulation

### **54. Condition:** • [Too little](#)

While wall insulation was not verified, it is likely with this age, type of wall finishes and history of home, that there is little or no insulation in the exterior walls. If wall cavity is sufficient, a blown in type of insulation such as cellulose could be installed. Consult an insulation specialist for advice.

**Implication(s):** Increased heating and cooling costs | Reduced comfort

**Location:** Throughout

**Task:** Upgrade

**Time:** Discretionary

# INSULATION AND VENTILATION

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING


**INSULATION**

PLUMBING

INTERIOR

APPENDIX

REFERENCE



[Click on image to enlarge.](#)



## Description

**Water supply source:** • Public

**Service piping into building:**

- [Galvanized steel](#)

Scraping of pipe surface upstream of meter shows a grey surface which appears to be galvanized steel. This area is difficult to access.




*Galvanized steel*

**Supply piping in building:** • [Copper](#)

**Main water shut off valve at the:**

- Front of the basement



*Water supply*

**Water heater fuel/energy source:** • [Electric](#)

**Water heater type:** • Owned

**Water heater manufacturer:**

• General Electric

*Model number:* GE60T6CB00 *Serial number:* 0102J17960

**Tank capacity:** • 270 Litres

**Water heater approximate age:** • 10 years

**Typical life expectancy:** • 8 to 12 years

**Waste piping in building:** • [ABS plastic](#)

**Floor drain location:** • Near laundry area

## Recommendations

### SUPPLY PLUMBING \ Supply piping in building


**55. Condition:** • [Poor pressure or flow](#)

Bathtub

**Implication(s):** Reduced water pressure and volume

**Location:** Bathroom


**Task:** Upgrade service piping to copper



## Galvanized steel pipe

rusting of galvanized pipe can greatly reduce water pressure and will eventually cause leaks as rust creates holes in the pipe walls

problems are likely to occur soonest on pipes carrying hot water, horizontal pipes and at threaded (thinner) sections



[Click on image to enlarge.](#)

## WATER HEATER \ Life expectancy

56. Condition: • [Near end of life expectancy](#)

Budget for replacement of water heater.

## WATER HEATER \ Temperature/pressure relief valve


57. Condition: • [Discharge tube too short](#)

Implication(s): Scalding

Location: Basement Furnace Room

Task: Provide - have plumber install correct pipe and do a service check on water heater.

Time: Immediate



[Click on image to enlarge.](#)



*Discharge tube too short*

**58. Condition:** • [Discharge tube threaded](#)

The danger of a threaded end is that someone may be tempted to screw on a cap, which would mean the relief valve would not discharge in case of high temperature or pressure.

**Implication(s):** Steam explosion

**Task:** Replace with pipe extended to within 6-12" of floor

**Time:** Immediate

**WASTE PLUMBING \ Floor drain**

**59. Condition:** • Covered. Owner advised location of drain so it could be uncovered for inspection.

**Implication(s):** Carpet over drain will impair drainage if floor floods.

**Location:** Laundry Area

**Task:** Make sure drain is exposed at all times.

**Time:** Immediate



*Floor drain*

## FIXTURES AND FAUCETS \ Faucet

### **60. Condition:** • [Loose](#)

Tap mount is loose due to rotted counter top and tap swivel is stiff.

**Location:** Kitchen first floor

**Task:** Replace at same time counter is replaced

## FIXTURES AND FAUCETS \ Hose bibb

### **61. Condition:** • [Damage](#)

Have qualified plumber replace bent pipe. Avoid long unsupported pipe runs.

**Implication(s):** Leakage | Equipment inoperative

**Location:** Front Exterior

**Task:** Repair



*Bent pipe going to outside tap*



## Description

### Major floor finishes:

- [Hardwood](#)
- [Resilient](#)
- ..... (bathroom linoleum)
- Vinyl
- Tile

### Major ceiling finishes: • [Plaster/drywall](#)

**Windows:** • [Fixed](#) • [Single/double hung](#) • [Sliders](#) • Aluminum

### Glazing:

- [Single](#)
- [Double](#)



*Age of windows - prox 24 yrs*

**Exterior doors - type/material:** • Hinged • [Storm](#) • [Solid wood](#)


## Recommendations

### CEILINGS \ Plaster or drywall

**62. Condition:** • Cracked

**Location:** Master Bedroom

**Task:** Monitor for deterioration



*Ceiling crack*

## WINDOWS \ Sashes

**63. Condition:** • Pane installed backwards

**Location:** South Bedroom outer pane

**Task:** Correct

## WINDOWS \ Hardware

**64. Condition:** • [Broken](#)

latches

**Implication(s):** Cosmetic defects | System inoperative or difficult to operate

**Location:** North and South Bedrooms

**Task:** Repair



*Broken latch. Note exterior pane backwards*

## WINDOWS \ Storms and screens

### 65. Condition: • [Missing](#)

Install window screens where missing.

**Implication(s):** Chance of pests entering house | Increased heating costs | Reduced comfort

**Location:** West First Floor Dining Room

## DOORS \ Doors and frames

### 66. Condition: • Mildew

**Implication(s):** excess moisture and/or lack of air circulation

**Location:** Basement Laundry Area

**Task:** Improve



### 67. Condition: • [Stiff](#)

.....outer sliding door very hard to move.

**Implication(s):** Reduced operability

**Location:** Rear Kitchen

**Task:** Repair or replace

### 68. Condition: • [Weatherstripping missing or ineffective](#)

**Implication(s):** Chance of water entering house | Increased heating and cooling costs | Reduced comfort

**Location:** Front First Floor Hallway

**Task:** Provide

**Time:** Discretionary

## CARPENTRY \ Countertops

### 69. Condition: • [Loose or missing pieces](#)

Deterioration of countertop is causing it to sag behind the sink, breaking the seal at the kitchen tap mount. This promotes further water damage when water goes under the tap mount.

**Location:** Kitchen first floor

**Task:** Replace counter



*Counter sagging under tap*


### 70. Condition: • [Rotted substrate](#)

Water damage to counter at kitchen sink taps

**Location:** Kitchen First floor

**Task:** Replace

**Time:** When remodelling



[Click on image to enlarge.](#)



*Rotted counter under kitchen sink*

## STAIRS \ Spindles or balusters


71. Condition: • [Loose](#)

Implication(s): Fall hazard

Location: First Floor Dining Room

Task: Repair

Time: Immediate



[Click on image to enlarge.](#)





*Loose baluster top*

## **BASEMENT \ Wet basements - vulnerability**

**72. Condition:** • Check drains

**Implication(s):** Drain in laundry area floor is far away from water heater. If water heater leaks, entire basement may get wet. Recommend drain be installed close to water heater. It is possible there is a second drain in the basement that is covered. Have drain lines inspected and tested to ensure they are in good condition, properly installed and fully functional.

**Location:** Throughout Basement

**Task:** Further evaluation by drain specialist

## **EXHAUST FANS \ Exhaust duct**

**73. Condition:** • [Termination point not found](#)

Fans exhausting moist air inside walls and ceilings can cause water damage.

**Implication(s):** Chance of condensation damage to finishes and/or structure

**Location:** Basement Bathroom

**Task:** Ensure fan is properly terminated to outside.

**Time:** Immediate

**END OF REPORT**

# ABOUT YOUR HOUSE

CE 3

## Asbestos

### WHAT IS ASBESTOS?

Asbestos is a natural mineral with unusual qualities. It is strong enough to resist high temperatures, chemical attack and wear. A poor conductor, it insulates well against heat and electricity.

Asbestos crystals become long, flexible, silky fibres, so it can be made into a wide variety of forms. It can be spun into yarn, woven into cloth or braided into rope. Asbestos can also be added to materials as diverse as cotton and cement.

This combination of properties gives asbestos performance capabilities that are difficult to match.

### WHAT HAS ASBESTOS BEEN USED FOR?

Asbestos has been used in hundreds of applications and products over the past 4,500 years. The ancient Greeks wove it into oil lamp wicks, funeral shrouds and ceremonial tablecloths.

During the 1800s, it insulated the hot engines, boilers and piping that powered the Industrial Revolution.

For half a century, until the 1980s, asbestos was used in office buildings, public buildings and schools. It insulated hot water heating systems, and was put into walls and ceilings as insulation against fire and sound.

Asbestos has also been widely used in transportation and electrical appliances, frequently mixed with, and encased in, other materials.

Asbestos has also been found in many products around the house. It has been used in clapboard; shingles and felt for roofing; exterior siding; pipe and boiler covering; compounds and cement, such as caulk, putty, roof patching, furnace cement and driveway coating; wallboard; textured and latex paints; acoustical ceiling tiles and plaster; vinyl floor tiles; appliance wiring; hair dryers; irons and ironing board pads; flame-resistant aprons and electric blankets; and clay pottery. Loose-fill vermiculite insulation may contain traces of "amphibole" asbestos.

### HOW HAS THE USE OF ASBESTOS CHANGED?

When it became evident that regular exposure to asbestos on the job involved health risks, the public became more concerned about exposure to asbestos in offices and schools, and, eventually, about all asbestos products.

This concern has led to a dramatic decline in asbestos use since the early 1980s. The use of asbestos insulation in buildings and heating systems has virtually disappeared. Residential use, for roofing, flooring and appliances, continues to decrease.

While alternative products are being developed to replace asbestos, products sold today containing asbestos are regulated under the *Hazardous Products Act*. Asbestos can be used safely, and public concern has led to improved product design and manufacture. Asbestos is now better encapsulated and sealed to reduce the escape of fibres.

**About Your House****Asbestos**

Asbestos is valuable in many applications because it has been difficult to find comparable substitute materials. For example, it is still an important component of brake lining and clutch facings.

### WHAT HEALTH PROBLEMS ARE ASSOCIATED WITH EXPOSURE TO ASBESTOS?

Health Canada states that the asbestos content of a product does not indicate its health risk.

Asbestos poses health risks only when fibres are in the air that people breathe. Asbestos fibres lodge in the lungs, causing scarring that can ultimately lead to severely impaired lung function (asbestosis) and cancers of the lungs or lung cavity.

Concern for the health of asbestos workers was expressed as long ago as the late 1800s. The risks became more evident in the late 1960s, when workers who had been heavily exposed 20 to 30 years earlier showed increased incidence of lung disease. Occupational exposure is now strictly regulated by provincial governments.

### WHEN CAN ASBESTOS BE A PROBLEM IN THE HOME?

Today, far fewer products in the home contain asbestos. Current products that do contain the material are better made to withstand wear and use.

However, frequent or prolonged exposure to asbestos fibres may still bring health risks. This can happen with the release of fibres into the air when asbestos-containing products break down, either through deterioration as they age or when they are cut. People can put themselves at risk—often without realizing it—if they do not take proper precautions when repairs or renovations disturb asbestos-containing materials. This can occur in a number of situations:

- Disturbing loose-fill vermiculite insulation which may contain asbestos
- Removing deteriorating roofing shingles and siding containing asbestos, or tampering with roofing felt that contains asbestos

- Ripping away old asbestos insulation from around a hot water tank
- Sanding or scraping vinyl asbestos floor tiles
- Breaking apart acoustical ceilings tiles containing asbestos
- Sanding plaster containing asbestos, or sanding or disturbing acoustical plaster that gives ceilings and walls a soft, textured look
- Sanding or scraping older water-based asbestos coatings such as roofing compounds, spackling, sealants, paint, putty, caulking or drywall
- Sawing, drilling or smoothing rough edges of new or old asbestos materials

**About Your House**

## Asbestos

**HOW TO MINIMIZE THE ASBESTOS RISKS IN THE HOME?**

If you do not know if products in your home contain asbestos, have an experienced contractor inspect them. If there is asbestos, the best interim measure (unless the product is peeling or deteriorating) is to seal the surface temporarily so that fibres will not be released into indoor air. If the product is already protected or isolated, simply leave it alone.

It is a complex and expensive matter to remove asbestos, and should be done by an experienced contractor.

When disturbing an asbestos product, maximum precautions must be taken to safeguard the workers and anybody else who may be nearby. Asbestos dust must remain within the work area so that it cannot be breathed in by unprotected persons.

It is essential to take adequate precautions. Everybody who works with asbestos should always wear an approved face mask and gloves, along with protective clothing. Be sure to tape sleeve and trouser cuffs, and wash clothes separately after use. Keep the work area moist to keep dust and fibre particles from floating into the air. Isolate the work space.

Reduce the air pressure to prevent asbestos fibres from escaping from the work area, and filter the exhaust air. Dispose of all waste appropriately, according to the guidelines of your provincial department of the environment. Other removal methods may be warranted for special conditions- consult an expert.

**VERMICULITE INSULATION**

Some vermiculite may contain asbestos.

- Do not disturb loose-fill vermiculite insulation.
- Do not store items near vermiculite insulation, if the insulation can be disturbed.
- Do not allow children near loose fill vermiculite insulation.
- If activities are planned that will disturb vermiculite, consult a certified asbestos removal company.



Figure 1 Vermiculite Insulation

**About Your House**

## Asbestos

**WHERE CAN YOU GET  
MORE INFORMATION  
ON ASBESTOS?**

For information on how to minimize exposure to asbestos refer to: *It's Your Health – Vermiculite Insulation Containing Asbestos*, Health Canada.

**<http://www.hc-sc.gc.ca>**

For information on occupational exposure to asbestos, contact: Canadian Centre for Occupational Health and Safety (CCOHS)

135 Hunter Street East  
Hamilton, ON L8N 1M5

Phone: 1 905 570-8094

Toll-Free: 1 800 668-4284

Fax: 1 905 572-2206

Web Site: [www.ccohs.ca](http://www.ccohs.ca)

For contractors who specialize in asbestos abatement and removal, look in the Yellow Pages™ under "Asbestos".

U.S. EPA's Asbestos Home Page at:  
**<http://www.epa.gov/oppt/asbestos/index.html>**

**To find more About Your House fact sheets plus a wide variety of information products, visit our website at [www.cmhc.ca](http://www.cmhc.ca). You can also reach us by telephone at 1-800-668-2642 or by fax at 1-800-245-9274.**

**Priced Publications**

*Building Materials for the Environmentally Hypersensitive*

Order No. 61089

*The Clean Air Guide: How to Identify and Correct*

*Indoor Air Problems in Your Home*

Order No. 61082

**Free Publications**

**About Your House** fact sheets

*Carbon Monoxide*

Order No. 62046

*Assessing the Comfort and Safety of your Home's*

*Mechanical Systems*

Order No. 62266

*Wood Heat Safety in an Emergency*

Order No. 60339

*Hiring a Contractor*

Order No. 62277

©1996, Canada Mortgage and Housing Corporation  
Printed in Canada  
Produced by CMHC  
Revised 1999, 2001, 2004, 2005, 2007

03-08-07

Although this information product reflects housing experts' current knowledge, it is provided for general information purposes only. Any reliance or action taken based on the information, materials and techniques described are the responsibility of the user. Readers are advised to consult appropriate professional resources to determine what is safe and suitable in their particular case. Canada Mortgage and Housing Corporation assumes no responsibility for any consequence arising from use of the information, materials and techniques described.



ADVANCED AND EVER ADVANCING **mitsubishi electric**



DUCTLESS SPLIT-TYPE AIR CONDITIONERS

No.OB202

## TECHNICAL & SERVICE MANUAL

Wireless type


Models

**MS09NW×2 •MUM18NW**

### CONTENTS

1. FEATURES .....	2
2. TECHNICAL CHANGES .....	3
3. PART NAMES AND FUNCTIONS .....	3
4. SPECIFICATIONS .....	4
5. DATA .....	5
6. OUTLINES AND DIMENSIONS .....	9
7. WIRING DIAGRAM .....	10
8. REFRIGERANT SYSTEM DIAGRAM .....	11
9. TROUBLESHOOTING .....	12
10. DISASSEMBLY INSTRUCTIONS .....	14
11. PARTS LIST .....	17
12. OPTIONAL PARTS .....	18

NOTE : For parts list, please refer to the following manuals.  
MS09NW → OB192



The Slim Line.  
From Mitsubishi Electric.




**Mr.SLIM**

1

FEATURES

This “2 to 1” Multi system consists of a single outdoor unit with two compressors that permit up to two indoor units to be installed separate rooms, each with its own controller.



Cooling Capacity (BTU/h)

Operation	Indoor unit	
	MS09NW	MS09NW
1 Indoor Unit Operation	8,400	—
	—	8,400
2 Indoor Unit Operatin	8,400	8,400

1.SPACE-SAVING LAYOUT

Two indoor units are served by a single outdoor unit whose installation requires only minimum space. This allows equipment installed outside the house to be arranged in a neat, space-saving layout.

2.FLEXIBLE INSTALLATION OF INDOOR UNITS


Each indoor unit can be connected to piping up to 49 feet in length, providing plenty of freedom in determining the best locations for installation.

3.AUTO-RESTART FUNCTION

The auto restart function restarts the equipment when power is restored following an outage automatically. Operation resumes in the mode in which the equipment was running immediately before the outage.

HIGH PERFORMANCE ROTARY COMPRESSOR

The advanced design of Mitsubishi Electric's powerful and energyefficient rotary compressor results in lower operating costs and longer service life.



## 2


## TECHNICAL CHANGES

**MSM18EW → MSM18NW**

1. Indoor unit has been changed.
2. Outdoor unit has been changed.
3. Remove controller has been changed.  
(The timer function was changed to the clock timer function.)
4. Indoor auto vave has been adopted.
5. Outdoor fan motor has been changed.  
(SGW-60F-AC→RA6W60-AA)
6. The varistor and the fuse have been added to electric circuit of the outdoor unit.

## 3

## PART NAMES AND FUNCTIONS

**OUTDOOR UNIT****MUM18NW**

## 4

## SPECIFICATIONS

Items		Model	MSM18NW	
			SINGLE	DOUBLE
Cooling capacity	※1 BTU/h		8,400	8,400X2
Power consumption	※1 W		850	1,700
EER (Double unit operation)			9.9	
SEER (Double unit operation)			10.0	
INDOOR UNIT MODEL			MS09NW×2	
External finish			White	
Power Supply		V, Hz, Phase	115,60,1	
Max. fuse size (time delay)		A	15	
Min. ampacity			0.5	
Fan motor		F.L.A	0.37	
Airflow	Dry	CFM	208-265-328	
	Wet	CFM	177-226-279	
Moisture removal		(Pints/h)	—	
Cond. drain connection OD		in.	5/8	
Dimensions	W	in.	32-1/16	
	D	in.	7-3/16	
	H	in.	10-13/16	
Weight		lbs.	18	
OUTDOOR UNIT MODEL			MUM18NW	
External finish			Munsell 5Y6.5/1	
Power supply		V, Hz, Phase	208/230,60,1	
Max. fuse size (time delay)		A	15X2	
Min. ampacity			14	14+13
Fan motor		F.L.A	1.0	
Compressor	Model		KH122WES×2	
	Winding resistance (at 68°F) Ω		C-R 0.98 C-S 2.21	
	R.L.A		10X2	
	L.R.A		37X2	
Refrigerant control			Capillary tube	
Dimensions	W	in.	33-1/2	
	D	in.	11-7/16 (12-5/8)	
	H	in.	23-7/8	
Weight		lbs.	122	
REMOTE CONTROLLER			Wireless type	
Control voltage (be built-in transformer)			12V DC	
REFRIGERANT PIPING			Not supplied (optional parts)	
Pipe size	Liquid	in.	1/4	
	Gas	in.	3/8	
Connection method	Indoors		Flared	
	Outdoors		Flared	
Between the indoor & outdoor units	Height difference	ft	Max. 25	
	Piping length	ft	Max. 49	

Notes ※1. Rating conditions (cooling) — Indoor : 80°FDB, 67°FWB, Outdoor : 95°FDB, 75°FWB

### Operating Range

		Indoor air intake temperature	Outdoor air intake temperature
Cooling	Maximum	90°FDB,71°FWB	115°FDB
	Maximum	67°FDB,57°FWB	67°FDB

## 5

## DATA

### 1.PERFORMANCE DATE (ONE INDOOR UNIT WITH ONE OUTDOOR UNIT)

**MS09NW × 2**  
**MUM18NW**

Models	Indoor air IWB (°F)	Outdoor intake air DB temperature(°F)														
		75			85			95			105			115		
		TC	SHC	TPC	TC	SHC	TPC	TC	SHC	TPC	TC	SHC	TPC	TC	SHC	TPC
MS09NW	71	10.3	5.93	0.76	9.61	5.55	0.83	9.03	5.21	0.89	8.4	4.84	0.94	7.73	4.46	0.98
	67	9.74	6.91	0.71	9.07	6.44	0.79	8.4	5.95	0.85	7.81	5.55	0.90	7.18	5.10	0.94
	63	9.16	7.72	0.68	8.48	7.16	0.75	7.9	6.66	0.81	7.18	6.06	0.87	6.55	5.53	0.90

Notes 1. IWB : Intake air wet-bulb temperature  
TC : Total Capacity (x10<sup>3</sup> Btu/h), SHC : Sensible Heat Capacity (x10<sup>3</sup> Btu/h)  
TPC : Total Power Consumption (kW)  
2. SHC is based on 80°F of indoor intake air DB temperature.


### 2) COOLING CAPACITY CORRECTIONS

MODEL	Refrigerant piping length (one way)		
	25ft (std)	40ft	49ft
MS-09NW	1.0	0.954	0.927

### 1.PERFORMANCE CURVE (ONE INDOOR UNIT WITH ONE OUTDOOR UNIT)

NOTE : A point on the curve shows the reference point.

**MS09NW**  
**MUM18NW**









**3.CONDENSING PRESSURE AND SUCTION PRESSURE  
(ONE INDOOR UNIT WITH ONE OUTDOOR UNIT)**

Data is based on the condition of indoor humidity 50%. Air flow should be set at HI. A point on the curve shows the reference point.


**MS09NW  
MUM18NW**



## 2.STANDARD OPERATION DATA

Model			MSM18NW	
			Single	Double
Item			Cooling	
Total	Capacity	Btu/h	8,400	8,400X2
	SHF	—	0.71	0.71
	Input	kW	0.85	1.70
Electrical circuit	Indoor unit model		MS09NW	
	Power supply (V,H <sub>z</sub> ,φ)		115-60-1	
	Input	kW	0.035X2	
	Fan current	A	0.34X2	
	Outdoor unit model		MUM18NW	
	Power supply (V,H <sub>z</sub> ,φ)		208/230-60-1(3-wire)	
	Input	kW	0.815	1.63
	Comp. current	A	6.64	7.16X2
	Fan current	A	1.0	
Refrigerant circuit	Condensing pressure	psi-G	260	270
	Suction pressure	psi-G	75	75
	Discharge temperature	°F	194	191
	Condensing temperature	°F	116	118
	Suction temperature	°F	64	54
	Comp. shell bottom temp.	°F	172	
	Ref. pipe length	ft	25X2	
	Refrigerant charge	—	1lds 14ozX2	
Indoor side	Intake air temperature	DB	°F	80
		WB	°F	67
	Discharge air temperature	DB	°F	60
		WB	°F	57
	Fan speed	rpm	1,230	
	Airflow (Hi)	CFM	279	
Outdoor side	Intake air temperature	DB	°F	95
		WB	°F	—
	Fan speed	rpm	900	
	Airflow	CFM	1,150	

## 3.POWER SUPPLY MSM18NW



## 4.OPERATING RANGE

### (1)POWER SUPPLY

	Models	Rating	Guaranteed Voltage
Indoor unit	MS09NW	115V 60Hz 1 $\phi$	Min. 103v—Max. 127V
Outdoor unit	MUM18NW	208/230V 60Hz 1 $\phi$ (3wires)	Min. 198V 208V 230V Max. 253V -----+-----+-----+-----

### (2)OPERATION


Function	Intake air temperature Condition	Indoor		Outdoor	
		DB (°F)	WB (°F)	DB (°F)	WB (°F)
Cooling	Standard temperature	80	67	95	—
	Maximum temperature	95	71	115	—
	Minimum temperature	67	57	67	—
	Maximum humidity	78%		—	

## 5.ADDITIONAL REFRIGERANT CHARGE (R-22(oz))

Model	Outdoor unit precharged (up to 25ft)	Refrigerant piping length (one way)					
		25ft	30ft	33ft	40ft	45ft	49ft
MS09NWx2 MUM18NW	1 lbs 14 oz X2	0	1	1	2	2	3

## 6.MAX. REFRIGERANT PIPING LENGTH & MAX. HEIGHT DIFFERENCE

### MSM18NW



## 7.PIPING PREPARATION

① Table below shows the specifications of pipes commercially available.

UNIT No.	Pipe	Outside diameter	Insulation thickness(in)	Insulation material
		inch		
[A] and [B] UNIT	For liquid	1/4	1/4	Heat resisting foam plastic 0.045 specific gravity
	For gas	3/8	1/4	

② Ensure that the 2 refrigerant pipes are well insulated to prevent condensation.


③ Refrigerant bending radius must be 10cm or more.

## 6

## OUTLINES AND DIMENSIONS

MODEL : MUM18NW  
OUTDOOR UNIT

Unit : inch




NOTE : The symbol  $\phi$  indicates diameter.

## 7

## WIRING DIAGRAM

### OUTDOOR

### MODEL MUM18NW WIRING DIAGRAM



SYMBOL	NAME	SYMBOL	NAME	SYMBOL	NAME
C1,2	COMPRESSOR CAPACITOR	MF	FAN MOTOR(INNER THERMOSTAT)	51C1,2	OVERCURRENT RELAY
C3	FAN MOTOR CAPACITOR	NR	VARISTOR	52C1,2	COMPRESSOR CONTACTOR
F	FUSE(3.0A)	TB1~3	TERMINAL BLOCK		
MC1,2	COMPRESSOR	X1,2	FAN MOTOR RELAY		


NOTE: 1. Use copper conductors only (For field wiring).

2. Symbols below indicate.

○: Terminal block, □: Connector

3. \* shows the terminals with a lock mechanism, so they cannot be removed when you pull the lead wire.

Be sure to pull the wire by pushing the locking lever (projected part) of the terminal with a finger.



1. Slide the sleeve.
2. Pull the wire while pushing the locking lever.



# APPENDIX

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX


REFERENCE

8

## REFRIGERANT SYSTEM DIAGRAM

MS09NW X 2/MUM18NW

Unit : inch



## 9

## TROUBLESHOOTING

### MUM18NW



#### 9-1 Cautions on troubleshooting

##### 9-1-1 Before troubleshooting, check the followings:

- 1) Check the power supply voltage.
- 2) Check the indoor/outdoor connecting wire for mis-wiring.

##### 9-1-2 Take care the followings during servicing.

- 1) Before servicing the air conditioner, be sure to first turn off the remote controller to stop the main unit, and then after confirming the horizontal vane is closed, disconnect the breaker.
- 2) When removing the P.C. board, hold the edge of the board with care NOT to apply stress on the components.
- 3) When connecting or disconnecting the connectors, hold the housing of the connector. DO NOT pull the lead wires.




#### 9-2 Trouble criterion of main parts

Part name	Check method and criterion	Figure										
Compressor	<p>Measure the resistance between the terminals with a tester. (Coil wiring temperature-10°C ~ 40°C)</p> <table border="1"> <thead> <tr> <th></th><th>Normal</th><th>Abnormal</th></tr> </thead> <tbody> <tr> <td>C-R</td><td>0.86~1.06Ω</td><td rowspan="2">Opened or short-circuited</td></tr> <tr> <td>C-S</td><td>1.94~2.39Ω</td></tr> </tbody> </table>		Normal	Abnormal	C-R	0.86~1.06Ω	Opened or short-circuited	C-S	1.94~2.39Ω			
	Normal	Abnormal										
C-R	0.86~1.06Ω	Opened or short-circuited										
C-S	1.94~2.39Ω											
Outdoor fan motor	<p>Measure the resistance between the terminals with a tester. (Coil wiring temperature-10°C ~ 40°C)</p> <table border="1"> <thead> <tr> <th></th><th>Normal</th><th>Abnormal</th></tr> </thead> <tbody> <tr> <td>WHT-BLK</td><td>17.6~21.6Ω</td><td rowspan="3">Opened or short-circuited</td></tr> <tr> <td>BLK-YLW</td><td>9.1~11.3Ω</td></tr> <tr> <td>YLW-RED</td><td>9.1~11.3Ω</td></tr> </tbody> </table>		Normal	Abnormal	WHT-BLK	17.6~21.6Ω	Opened or short-circuited	BLK-YLW	9.1~11.3Ω	YLW-RED	9.1~11.3Ω	
	Normal	Abnormal										
WHT-BLK	17.6~21.6Ω	Opened or short-circuited										
BLK-YLW	9.1~11.3Ω											
YLW-RED	9.1~11.3Ω											





## Check of outdoor unit

Compressor and outdoor fan do not operate.(Only indoor fan operates.)





## 10 DISASSEMBLY INSTRUCTIONS

### OUTDOOR UNIT MUM18NW



OPERATING PROCEDURE	PHOTOS
<p><b>1. Removing of the cabinet</b></p> <p>(1) Remove the set screws of the valve cover to remove the valve cover as shown in Photo 2.</p> <p>(2) Remove the set screws of the side panel to remove the side panel and cabinet.</p>	<p><b>Photo 1</b></p>  <p><b>Photo 2</b></p> 
<p><b>2. Removing the propeller</b></p> <p>(1) Remove the propeller nut.</p> <p>(2) Loosen the propeller in the rotating direction.</p> <p>(3) Pull the propeller forward.</p> <p><b>Note:</b></p> <ul style="list-style-type: none"> <li>To set the propeller, fit the cut on the shaft to the mark on the propeller.</li> </ul>	<p><b>Photo 3</b></p>  <p><b>Photo 4</b></p> 

INTRODUCTI	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

OPERATING PROCEDURE		PHOTOS	
<p><b>3. Removing the outdoor fan motor.</b></p> <p>(1) Remove the cabinet. (Refer to 1)</p> <p>(2) Remove the propeller. (Refer to 2)</p> <p>(3) Disconnect the connector remove the clamp of outdoor fan motor lead wire.</p> <p>(4) Remove the screws fixing the outdoor fan motor.</p>		<p><b>Photo 5</b>      Set screws of the relay panel</p>  <p>Clamp      Connector</p>	
		<p><b>Photo 6</b>      Screws</p>  <p>Clamp</p>	



INTRODUCTI	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
APPENDIX	REFERENCE								

OPERATING PROCEDURE		PHOTOS	
<p><b>4. Removing the compressor</b></p> <p>(1) Disconnect the cord connector. (See Phot 5)</p> <p>(2) Remove the set screws of the relay panel.</p> <p>(3) Remove the set nuts of the terminal cover.</p> <p>(4) Pull up the compressor.</p> <p>(5) Pull out the lead wires from the compressor terminal to remove overcurrent relay.</p> <p>(6) Remove set nuts of the compressor base.</p> <p>(7) Remove the low pressure side welded part and high pressure side welded part using a burner.</p> <p><b>Note:</b></p> <ul style="list-style-type: none"><li>● Before using a welder, release gas inside the unit and make sure that the gauge pressure shows 0 kg/cm<sup>2</sup>.</li><li>● During welding, open the charge plug because pressure rises due to expansion by heat</li></ul>		<p><b>Photo 7</b></p> <p>Set nuts of the terminal cover</p> 	
		<p><b>Photo 8</b></p>  <p>Nuts                      Nuts</p>	


## 11

## PARTS LIST

## OUTDOOR UNIT PARTS

## MUM18NW

Refer to MS09EW for indoor unit.



Part number that are circled is not shown in the illustration.

No.	Parts No.	Parts Name	Symbol in Wiring Diagram	Q'ty/unit	Remarks
				MUM18NW	
1	T2W 382 342	CONTACTOR	52C1,52C2	2	G4F11123T-M
2	T2W 462 232	CABINET		1	
3	T2W 667 249	SIDE PANEL		1	
4	T2W 739 245	SERVICE PANEL		1	
5	T2W 466 509	OUTDOOR NOZZLE		1	
6	T2W A75 301	OUTDOOR FAN MOTOR	MF	1	RA6W60-□□
7	R01 093 115	PROPELLER		1	
8	T2W 903 353	COMPRESSOR CAPACITOR	C1,C2	2	55 $\mu$ F 220V
9	T2W 466 342	OUTDOOR FAN RELAY	X1,X2	2	
10	T2W E47 378	OUTDOOR TERMINAL BLOCK	TB1	1	
11	T2W 464 340	OVERCURRENT RELAY	51C1,51C2	2	
12	T2W 466 350	OUTDOOR FAN CAPACITOR	C3	1	8 $\mu$ F 220V
13	T2W 466 630	OUTDOOR HEAT EXCHANGER		1	
14	M21 B90 641	CHARGE PLUG		2	
15	T2W 416 642	FUSIBLE PLUG		2	
16	T2W 460 662	VALVE (LIQUID) 1/4		1	
17	T2W 460 661	VALVE (GAS) 3/8		1	
18	T92 513 200	COMPRESSOR	MC1,MC2	1	8 $\mu$ F 220V
19	T2W 739 246	VALVE COVER		1	
20	M21 B93 936	CAPILLARY TUBE		2	Q0.12×Q0.055×43-5/16
21	T2W E42 375	TERMINAL BLOCK	TB2,3	1	
22	M21 020 378	TERMINAL BLOCK		1	
23	T2W 739 290	BASE ASSEMBLY		1	
24	T2W A96 641	CHARGE PLUG		2	


When servicing, cut the tube to the proper length as shown in the REFRIGERANT SYSTEM DIAGRAM see page 11.

## 12

## OPTIONAL PARTS

### 1. REFRIGERANT PIPES

The air conditioner has flared connections its indoor and outdoor sides.  
Please use the optional extension pipe as follows.

Model	Part No.	Pipe length	Pipe size O.D				Additional refrigerant charge R-22(Oz)
			Cross-section	A-Gas	B-Liquid	Insulation	
MS09NW	MAC - 440PI	10ft		3/8	1/4	C 13/16 D 1-1/16	0
	MAC - 441PI	16ft					
	MAC - 442PI	23ft					
	MAC - 443PI	33ft					1

# APPENDIX

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE

# APPENDIX

321 Typical Street, Toronto, ON    October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



The Slim Line.  
From Mitsubishi Electric.



Mr. SLIM

 **mitsubishi electric CORPORATION**

©Copyright 1997 MITSUBISHI ELECTRIC ENGINEERING CO.,LTD.  
Issued in Sep. 1997 NO.OB202 5011

New publication, effective Sep. 1997.  
Specifications subject to change without notice.

# APPENDIX

321 Typical Street, Toronto, ON October 2, 2012

Report No. 1016, v.3

[www.meticulousinspections.ca](http://www.meticulousinspections.ca)

INTRODUCTI

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

REFERENCE



## **MITSUBISHI ELECTRIC**

### HVAC Advanced Products Division

---

3400 Lawrenceville Suwanee Road • Suwanee, Georgia 30024  
Toll Free: 800-433-4822 • Toll Free Fax: 800-889-9904  
[www.mrslim.com](http://www.mrslim.com)

Specifications are subject to change without notice.



The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

## [1. Roofing, Flashings and Chimneys](#)

## [2. Exterior](#)

## [3. Structure](#)

## [4. Electrical](#)

## [5. Heating](#)

## [6. Cooling/Heat Pumps](#)

## [7. Insulation](#)

## [8. Plumbing](#)

## [9. Interior](#)

## [10. Appliances](#)

## [11. Life Cycles and Costs](#)

## [12. Supplementary](#)

[Asbestos](#)

[Radon](#)

[Urea Formaldehyde Foam Insulation \(UFFI\)](#)

[Lead](#)

[Carbon Monoxide](#)

[Mold](#)

[Household Pests](#)

[Termites and Carpenter Ants](#)

## [13. Home Set-up and Maintenance](#)

## [14. More About Home Inspections](#)

[ASHI Standards of Practice](#)

[CAHPI Standards of Practice](#)